Flammability Certificate 3018 Cube Geo Designtex

3018 Cube Geo was tested and met the following flammability requirements:

CA TB 117-2013



Quality Assurance & Compliance Testing Utilizing Textile & Related Technologies

19 West 36th Street, 10th Floor New York, NY 10018 Tel: 212 947 8391 Fax: 212 947 8719

www.vartest.com

ISO/ICC 17025 Third Party Test Report

DATE:

October 10, 2022

FILE: DESTEX.A100422B

CLIENT:

Design Tex Inc.

ATTN: Teesha Prezeau

357 County Ave Secaucus, NJ 07094

SAMPLE IDENTIFIED BY CLIENT AS:

Fabric Submitted

Ref #: 3018 201 / Cube Geo Turmeric

Lot #: 1033350-42851 Color Gold/Natural Multi

TEST PROCEDURES:

TEST RESULTS:

CALIFORNIA TECHNICAL BULLETIN 117-2013 SECTION 1 COVER FABRIC TEST

		CHAR LENGTH ******	OPEN FLAME *****	SMOULDER TIME OVER 45 MINUTES ********	
SPECIMEN	1:	13.5 mm	N	None	
SPECIMEN	2:	11.0 mm	N	N	
SPECIMEN	3:	11.0 mm	N	N	

RESULTS: PASS

A material is considered to pass or fail based on the following criteria:

- 1. A single mock-up test specimen fails to meet the requirements of this test Procedure if any of the following criteria occurs:
- a) The mock-up test specimen continues to smolder after the 45-minute test duration.
- b) A char develops more than 1.8 inches (45 mm) in any direction from the cigarette on the cover fabric measured from its nearest point.
- c) The mock-up test specimen transitions to open flaming.
- 2. The cover fabric passes the test if three initial mock-up specimens pass the test, i.e., the cigarettes burn their full length and the mock-ups are no longer smoldering.
- 3. If more than one initial specimen fails, the cover fabric fails the test.
- 4. If any one of the three initial specimens fails, repeat the test on an additional three specimens.
- 5. If all three additional specimens pass the test, the cover fabric passes the test.
 - If any one of the three additional specimens fails, the cover fabric fails the test.

